

Instruction to load CMP-10 firmware

Following items are required

CMP-10 with the paper roll in it with enough battery level

Serial cable

PC with Windows + Serial port

CMP10LOAD.EXE

Firmware data

CMP-10 side

Connect Serial cable to CMP-10 and PC

Turn CMP-10 while pressing LF switch and hold the LF switch for more than 6 second.

Then CMP-10 print "Flash Programing mode" after buzzer sounds.

PC side

Run CMP10LOAD.EXE

If you do not use COM1, please change the COM port.

Check "FIRMWARE".

Press BROWSE and choose Firmware data file.

When all of above are done, please press START.

Firmware loading will be finished in about 30 seconds.

Never turn the CMP-10 off during loading firmware.

After finishing firmware loading, please check firmware version by self test.